

件 Z10 是一种铸态的合金钢，其化学成分见表 2-10。

AWS -

13-ER-55-AO-ME



1. 焊接材料

1) 焊丝

2) 焊剂

图 2-10 铸态合金钢 Z10 与碳钢 A572-50 的埋弧焊

图例: 铸态合金钢 Z10 碳钢 A572-50




图 2-11 铸态合金钢 Z10 与碳钢 A572-50 的埋弧焊